Lecture 14: CNC machines and Control Programming

History of CNC

- 1949-US Air Force asks MIT to develop a "numerically controlled" machine.
- 1952-Prototype NC machine demonstrated (punched tape input)
- 1980-CNC machines (computer used to link directly to controller)
- 1990-DNC: external computer "drip feeds" control programmer to machine tool controller

Advantages of CNC

- Easier to program;
- Easy storage of existing programs;
- Easy to change a program
- Avoids human errors
- NC machines are safer to operate
- Complex geometry is produced as cheaply as simple ones
- Usually generates closer tolerances than manual machines

NC machines

Motion control is done by: servo-controlled motors



CNC terminology

BLU: basic length unit \rightarrow

smallest programmable move of each axis.

Controller: (Machine Control Unit, MCU) \rightarrow

Electronic and computerized interface between operator and m/c

Controller components:

- Data Processing Unit (DPU)
 - Input device [RS-232 port/ Tape Reader/ Punched Tape Reader]
 - Data Reading Circuits and Parity Checking Circuits
 - Decoders to distribute data to the axes controllers.
- 2. Control-Loops Unit (CLU)
 - Interpolator to supply machine-motion commands between data points
 - Position control loop hardware for each axis of motion

Types of CNC machines

• Based on Motion Type:

Point-to-Point or Continuous path

• Based on Control Loops:

Open loop or Closed loop

• Based on Power Supply:

Electric or Hydraulic or Pneumatic

• Based on Positioning System

Incremental or Absolute



Open Loop vs. Closed Loop controls

Open loop control of a Point-to-Point NC drilling machine



NOTE: this machine uses stepper motor control

Components





Two types of encoder configurations

Motion Control and feedback

Encoder outputs: electrical pulses (e.g. 500 pulses per revolution)

Rotation of the motor \rightarrow linear motion of the table: by the **leadscrew**

The pitch of the leadscrew: horizontal distance between successive threads

One thread in a screw → single start screw: Dist moved in 1 rev = pitch

Two threads in screw \rightarrow **double start screw**: Dist moved in 1 rev = 2* pitch

Example 1

A Stepping motor of 20 steps per revolution moves a machine table through a leadscrew of 0.2 mm pitch.

(a) What is the BLU of the system ?

(b) If the motor receives 2000 pulses per minute, what is the linear velocity in inch/min ?

Example 2

A DC servo-motor is coupled to a leadscrew (pitch 5mm) of a machine table. A digital encoder, which emits 500 pulses per revolution, is mounted on the leadscrew. If the motor rotates at 600 rpm, find

- (a) The linear velocity of the table
- (b) The BLU of the machine
- (c) The frequency of pulses emitted by the encoder.

Manual NC programming

Part program: A computer program to specify

- Which tool should be loaded on the machine spindle;
- What are the cutting conditions (speed, feed, coolant ON/OFF etc)
- The start point and end point of a motion segment
- how to move the tool with respect to the machine.

History of CNC

The RS274-D is a word address format

Each line of program == 1 **block**

Each block is composed of several instructions, or (words)



Appendix I

RS274-D format: Alphabets and their meanings.

ALPHABET ADDRESS FOR

А	Angular rotary table dimension around X axis		
В	Angular rotary table dimension around Y axis		
С	Angular rotary table dimension around Z axis		
D	Angular dimension around special axis/ 3rd feed function/function for tool		
	compensation		
E	Angular dimension around special axis/2nd feed function/function for tool		
	compensation		
F	feed rate function		
G	Preparatory function		
I	Interpolation parameter for thread lead parallel to X axis		
J	Interpolation parameter for thread lead parallel to Y axis		
K	Interpolation parameter for thread lead parallel to Z axis		
Μ	Miscellaneous function		
Ν	Sequence number		
0	Sequence number for secondary head (for dual machines, e.g Mill-Turn		
	machine.)		
Р	Third rapid traverse dimension		
Q	Second rapid traverse dimension		
R	First rapid traverse dimension/radius for constant surface speed calculations		
S	Spindle speed		
Т	Tool number function		
U	Rotary table velocity Secondary motion dimension parallel to X axis		
V	Rotary table velocity Secondary motion dimension parallel to Y axis		
W	Rotary table velocity Secondary motion dimension parallel to Z axis		
X	Primary X motion dimension		
Y	Primary Y motion dimension		
Ζ	Primary Z motion dimension		
[EB]	This is the last character on each block, the <u>End-of-B</u> lock character		
	(usually the return, or newline character).		

Appendix II RS274-D: Useful Preparatory Functions

G00 G01 G02 G03	Point to Point rapid positioning move Linear Interpolation Circular Interpolation, Arc CW (for 2D arcs in XY, XZ, or YZ planes) Circular Interpolation, Arc CCW (for 2D arcs in XY, XZ, or YZ planes)	Move in straight line at constant velocity Clockwise motion of tool with respect to workpiece, when viewing the plane of motion in -ve direction of the perpendicular axis Counter-Clockwise motion of tool wrt w/p, when viewing the plane of motion in -ve direction of the perpendicular axis
C 04	Dwell	
604	Dweil	a timed delay of programmed duration.
G06	Parabolic Interpolation	Programmed motion along a parabola; velocity of the axes is varied by the controller to maintain the feedrate as specified.
G08	Acceleration	Controlled velocity increase to programmed rate, starting immediately. Controlled velocity decrease to programmed rate.
G09	Deceleration	
G13-16	Axis Selection	
G17 G18 G19	XY plane selection for contouring XZ plane selection for contouring YZ plane selection for contouring	Used to identify plane for functions like circular interpolation, cutter compensation offset etc.
G28	Returning to zero position	
G33 G34 G35	Thread cutting, Constant lead Thread cutting, Increasing lead Thread cutting, Decreasing lead	For machines equipped with thread cutting The lead increases at a constant rate (linear) Decreases at constant rate (linear)
G40 G41	Cutter compensation cancel, Offset cancel Cutter compensation, Left	Cutter on left side of work surface, when viewing from cutter in the direction of relative cutter motion with displacement normal to the cutter path to adjust for the difference between actual and programmed cutter radii or diameters
G42	Cutter compensation, Right	As above
G43	Cutter offset, inside corner	Displacement normal to cutter path to adjust for the difference between actual and programmed cutter radii
G44	Cutter offset, outside corner	As above
G50-59	Reserved for adaptive control	
G70 G71	programming units in inches programming units in metric	Will get cancelled by use of G71, M02, or M30 Will get cancelled by use of G70, M02, or M30
G72 G73	3D Circular interpolation, CW 3D Circular interpolation, CCW	A mode where the cutter moves along a circular arc on the surface of a sphere. Velocities required to maintain feedrate are generated by the controller.
G74 G75	Cancel multi-quadrant circular interpolation Multi-quadrant circular interpolation	n
G80 G82 G83 G84	Cancel fixed cycle (Repeat of the previous Circle operation Drilling operation Square or rectangular operatio operation	block)

G85-89 Fixed cycles, Number 1, 2, .., 9

- G90 Absolute dimension inputs
- G91 Incremental dimension inputs

Input data is in absolute coordinates Input data is in form of incremental form, with respect to current position

- G92 Preload registers- set current tool position (affects only the block in which it appears.)
- G93 Inverse Time Feedrate (V/D)
- G94 Inches/mm per minute feedrate [Inches used if G70 was used earlier, mm if G71]
- G95 Inches/mm per spindle revolution feedrate
- G96 Constant surface speed, feet/meters per minute
- G97 Revolutions per minute (spindle speed)

Appendix III RS274-D: Useful Miscellaneous Functions

M00 Program temporary stop used in the last block of a program M01 Optional (planned) stop M02 End of program stops coolant, spindle, feedrate; resets the control/machine Spindle CW **M03** will advance a right handed screw into workpiece. Spindle CCW **M04** Spindle stop M05 Tool change M06 **M07** Coolant No. 2 ON Mist coolant **M08** Coolant No. 1 ON Flood coolant M09 Coolant stop M10 Clamp (vacuum start) M11 Unclamp(vacuum stop) M12 Synchronization code M13 Spindle CW and Coolant ON Spindle CCW and Coolant ON M14 M15 Motion + M16 Motion -M19 Oriented spindle stop M25 Rapid traverse to home position M30 End of data M31 Interlock bypass M39 Chuck M40 Chuck

M41-46 Gear changes, if assigned; otherwise unused.

- M47 Return to program start
- M48 Cancel M49
- M49 Bypass override

M58 Cancel M59

M59 Bypass CSS updating

a function which holds RPM constant at its value.

M90-98 reserved for user-defined controls

M99 Restart part program from the begining